

OUT54466

S E C R E T 162059Z

1964 NOV 16 21 47Z 25X1

1. CAMERA B-15 WAS USED IN MISSION 3966 FLOWN ON 13 NOVEMBER 1964. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: A PLUS DENSITY LINE IS PRESENT PARALLEL TO AND 3.3" FROM THE INBOARD EDGE IN THE FIRST 100 FRAMES OF THE MISSION. DENDRITIC STATIC TRACES OCCUR OCCASIONALLY ALONG THE INBOARD EDGE. A HEAT SPLICE IS LOCATED IN FRAME 1291 AND A MANUFACTURER'S SPLICE IN FRAME 1483.

C. 9L SIDE: THE OUTBOARD EDGE OF THE FILM IS SLIGHTLY WRINKLED ON FRAMES 890 THROUGH 916. A HEAT SPLICE IS MADE IN FRAME 1267 AND A MANUFACTURER'S SPLICE IN FRAME 2430 WITH ASSOCIATED STATIC TRACES AND FOG PRESENT ON FRAMES 2425 THROUGH 2435.

D. BOTH SIDES: EDGE STATIC AND EDGE FOG ARE PRESENT INTERMITTENTLY ALONG THE INBOARD AND OUTBOARD EDGES OF BOTH 9L AND 9R. ROLLER CHATTER APPEARS ALONG THE INBOARD EDGE INTERMITTENTLY THROUGHOUT. THE FRAMES ARE TITLED FROM 0001 THROUGH 2530.

E. NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES WERE OBSERVED ON THIS MISSION.

Declassification Review by NGA/DoD

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS DEGRADE OR OBSCURE APPROXIMATELY 15 PERCENT OF THE MISSION.

S E C R E T

/END OF MESSAGE/

SECRET

17 NOV 1964

B

FILMS

25X1
unclassified automatic
downgrading and
declassification